

HILTON HALL COMMUNITY CENTRE – FINAL WORK TO THE FRONT ENTRANCE – 26th SEPTEMBER 2013





THIS IS THE FINAL STAGE OF THE WORK NEEDED ON THE FRONT ENTRANCE AT HILTON HALL COMMUNITY CENTRE.

THE TWO DOWN-PIPES (DRAIN-PIPE COVERS) SITUATED AT BOTH SIDES OF THE FRONT ENTRANCE DOORS (MADE OF STEEL) HAVE HAD TO BE PAINTED FOUR TIMES NOW SINCE WE OPENED. AS CAN BE SEEN FROM THE FIRST COUPLE OF PHOTOS (ABOVE) THE PAINT KEEPS 'PEELING-OFF'

SO, IT WAS DECIDED TO CLAD THEM IN THE SAME WHITE THERMOPLASTIC MATERIAL THAT WAS USED FOR THE 'FACIA BOARDS'. THESE PANELS ARE RELATIVELY MAINTENANCE-FREE (AT LEAST NO MORE PAINTING NEEDED), JUST REGULAR CLEANING.

THE WORK WAS CARRIED OUT BY PETE LAMSDALE & DINO (WHO FITTED OUR WINDOWS). AND JUST AS BEFORE, THEY DID AN EXCELLENT JOB, MANY THANKS TO PETE & DINO.

THIS NOW FINISHES OFF THE WORK TO THE FRONT ENTRANCE, AND IS ONE MORE JOB DONE.



[CLICK ONTO THIS LINK TO GO BACK TO THE PHOTOGRAPHS PAGE](#)